

Annexure D

BUILDING SAFETY CERTIFICATE

No. 68/camp/AE-IV/26-27

Dated: 19/6/26

It is certified that the existing building SGS International School (name of the building or premises) at Baroth, Naulhal, Mathura.

(address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	9+1	X	X	X	X	X

The building is owned/occupied by SGS International School Baroth Naulhal Mathura (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public works department (Name of Department/ Govt.) on 19/6/26 (date of inspection) in the presence of Manager, SGS International School (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 19/6/26 for a period of 02 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. After this certificate is issued if any addition is made to
2. the building, then this certificate should be considered cancelled
3. and a new school safety certificate should be applied by the
4. school authorities

Issued on 19/6/26 at 02 by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

Name : Brinsh Kumar Sharma

Designation :

Name & Address of Department/Office : सहायक अभियन्ता